

Access Master Controller V1.001.000001.0

Release Notes





Legal Information

Copyright

© 2021 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to as "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third party. Without the prior written approval of the corresponding party, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

Trademarks



All other company names and trademarks mentioned herein are the properties of their respective owners.

Disclaimer

- These release notes are for reference only, and the actual product shall prevail.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, please refer to our final explanation.

I



Table of Contents

.egal Information	l
Release Notes	1
1.1 Overview	1
1.2 New Features	1
1.3 Fixed Bugs	1
1.4 New Feature Details	1
1.5 Compatibility	1
1.6 Software Environment	1
1.7 Pending Issues	2
1.8 Undate Guide	2



Release Notes

1.1 Overview

Item	Description	
Product model	Access Master Controller	
Version	V1.001.0000001.0	
Software		
package	DH_ASC2204C_Eng_V1.001.0000001.0.R.20210728.zip	
information		
OS requirement	None	
Release date	August 9, 2021	

1.2 New Features

The device is used indoors for card-swiping authorization of the access control system.

1.3 Fixed Bugs

Fixed bugs	Description
1	Fix bugs, improve performance, enhance security.

1.4 New Feature Details

None.

1.5 Compatibility

None.

1.6 Software Environment

Category	Model	Version
Tool	SmartPSS	2.0.2



1.7 Pending Issues

No.	Issue Description	Possible Result	How to Fix
1	14 items failed the ONVIF test.	Further commissioning is needed for ONVIF access.	Commission the device again for ONVIF access.
2	The user data has been distributed to the controller. When the controller is re-added after all controllers have been deleted by batch on the web, the controller is likely to go offline after going online or to go online slowly.	The controller will be deleted instantly after 100 fingerprints are distributed and then all be re-added. The controller will go online within 10 to 20 minutes.	 Wait for 10 minutes before going online again. Fix the problem in the next version.
3	Verification fails due to the lack of access platform for auto registration.	Auto registration needs to be commissioned after being customized on the project.	Finish the commissioning after auto registration is customized on the project.
4	Issues about Configtool: program version fails to display; wrong display of the device type.	Configtool issues.	Upgrade Configtool.

1.8 Update Guide

Refer to the following instructions when upgrading the device.

- Step 1 Open Configtool.
- Step 2 Search for the access IP.
- Step 3 Click **Update**.
- Step 4 Download the upgraded APP program.
- Step 5 Click Confirm.

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Address: No.1199, Bin'an Road, Binjiang District, Hangzhou, P.R. China

Postcode: 310053 Tel: +86-571-87688883

Fax: +86-571-87688815 Email: overseas@dahuatech.com

Website: www.dahuasecurity.com