



DH_VTO2&VTO4 Serials
V4.500.0000001.0.R.210713

Release Notes

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Legal Information

Copyright

© 2020 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to as "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third party. Without the prior written approval of the corresponding party, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

Trademarks

 and **HDCVI** are the trademarks or registered trademarks of Dahua.

All other company names and trademarks mentioned herein are the properties of their respective owners.

Disclaimer

- These release notes are for reference only, and the actual product shall prevail.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, please refer to our final explanation.

Table of Contents

Legal Information	I
Release Notes	1
1 Overview	1
2 New Features.....	1
3 Fixed Bugs	1
4 Compatibility.....	1
4.1 Program	1
4.2 Browser.....	1
4.3 Third Party Access.....	2
5 Software Environment.....	2
6 Pending Issues.....	2
7 Update Guide	2

Release Notes

1 Overview

Item	Description
Product model	DHI-VTO4202F-P-S2 DHI-VTO2202F-P-S2 DHI-VTO2201F-P
Version	V4.500.0000001.0.R.210713
Software package information	DH_VTOX20XF_MultiLang_PN_SIP_V4.500.0000001.0.R.210713.zip
Release date	

2 New Features

No.	Function
1	Supports H.265 and H.264 video coding
2	Supports 2-wire digital communication
3	Power over two-wire switch
4	Supports daisy chain topology
5	Compatibility 2-Wire Interface & RJ45 Interface

3 Fixed Bugs

Fixed bugs	Description
1	
2	
3	

4 Compatibility

4.1 Program

DH_VTOX20XF_MultiLang_PN_SIP_V4.500.0000001.0.R.210713

4.2 Browser

Not involved.

4.3 Third Party Access

Not involved.

5 Software Environment

Platform	Description
VTS	General_VTS5340B_MultiLang_NP_SIP_V4.500.0000000.5.R.201026
SDK	V3.051.0000001.2.R
H8900 PRO	General_DSS-H8900_Chn_Basic_V3.001.0000004.4.R.20200111.tar.gz
VTH	General_VTH542XH_MultiLang_SIP_V4.500.0000000.0.R.201203
Darwin	General_ICC-Common-VideoTalk_Basic_Chn_IS_V1.000.0000000.4.R.20200828
DSS-Pro	General_DSS-Pro_Win64_IS_V8.000.0000000.0.R.20200921
VDPconfig	General_ConfigTool_ChnEng_V5.000.0000001.3.R.20200912

6 Pending Issues

No.	Issue description	Possible result	How to fix
1	When the output resolution of the VTO is set to 720P, some old models of indoor monitor cannot play video streams.	Few old models of indoor monitors cannot be compatible with this VTO in 720P resolution mode.	Manually re-modify the video stream output resolution of the VTO to WVGA
	This version fixes some bugs, improves the product performance, and strengthens product security on the basis of the last version		

7 Update Guide

Refer to the Upgrade Guide.

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Address: No.1199, Bin'an Road, Binjiang District, Hangzhou, P.R. China

Postcode: 310053

Tel: +86-571-87688883

Fax: +86-571-87688815

Email: overseas@dahuatech.com

Website: www.dahuasecurity.com