



Nova  
V2.800.0000000.11.R.191030  
Release Notes

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

# Legal Information

## Copyright

© 2019 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to as "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third party. Without the prior written approval of the corresponding party, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

## Trademarks

 and **HDCVI** are the trademarks or registered trademarks of Dahua.

All other company names and trademarks mentioned herein are the properties of their respective owners.

## Disclaimer

- These release notes are for reference only, and the actual product shall prevail.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, please refer to our final explanation.

# Table of Contents

---

<b>Legal Information .....</b>	<b>I</b>
<b>Release Notes .....</b>	<b>1</b>
1.1 Overview .....	1
1.2 New Features .....	1
1.3 Fixed Bugs .....	1
1.4 Compatibility.....	1
1.4.1 Program .....	1
1.4.2 Browser.....	1
1.4.3 Third Party Access.....	2
1.5 Software Environment.....	2
1.6 Pending Issues.....	2
1.7 Update Guide.....	3

# Release Notes

## 1.1 Overview

Item	Description
Product model	Nova platform 2.800 baseline
Version	V2.800.0000000.11.R
Software package information	DH_SD-Mao-Nova_MultiLang_NP_Stream3_V2.800.0000000.11.R.191030.zip DH_SD-Mao-Nova_MultiLang_PN_Stream3_V2.800.0000000.11.R.191030.zip DH_SD-Mao-Nova_MultiLang_NP_Stream3-Xingenzong_V2.800.0000000.11.R.191030.zip DH_SD-Mao-Nova_MultiLang_PN_Stream3-Xingenzong_V2.800.0000000.11.R.191030.zip DH_SD-Chen-Nova_MultiLang_NP_Stream3_V2.800.0000000.11.R.191030.zip DH_SD-Chen-Nova_MultiLang_PN_Stream3_V2.800.0000000.11.R.191030.zip
OS requirement	None
Release date	November 7, 2019

## 1.2 New Features

None

## 1.3 Fixed Bugs

Number	Description
1	The "IP PTZ Camera" icon did not display on the login interface and live interface of the Neutral program for PTZ devices.

## 1.4 Compatibility

### 1.4.1 Program

Compatible with earlier versions, but later versions cannot return to versions earlier than 2.800.

### 1.4.2 Browser

For browsers of earlier versions, you need to download plugins; for later versions of Chrome, Firefox, and Edge (above 43), you do not need to download plugins, but part of the functions will be simplified or concealed.

Browsers used during test: win7 + IE11+ Edge 42.17134.1.0 + Chrome 70.0.3538.110 + Firefox 63.0.3 (64 bit).

### 1.4.3 Third Party Access

- CGI testing tool version: V3.01.5R
- ONVIF testing tool version: V18.12
- ONVIF: Supports ProfileG、 Profile T
- MILESTONE testing tool version: 2018R3 V12.3a Build: 9446
- GENETEC testing tool version: GUCT V5.7.607.40

## 1.5 Software Environment

Platform	Model	Version
NVR	DH-NVR-5432-I	DH_NVR5XXX-I_Chn_V3.215.0000010.0.R.20181016.zip
	DH-NVR4416-16 P-4KS2	DH_NVR4XXX-4KS2_Chn_V3.216.0000002.0.R.190102.zip
Client	SmartPSS	General_SMARTPSS-Win32_ChnEng_IS_V2.002.0000007.0.R.181023.zip
	Lechange	imou ios V3.11.0 imou Android V3.11.1.0215
	DMSS	IOS: 4.20.001 Android: 4.20.000
Tool	NetSDK	General_NetSDK_Chn_Win32_IS_V3.48.2.R.170712.7z
	NKB1000	General_NKB1000_ChnEng_V2.620.0000000.0.R.20180115.zip
	NKB5000	General_NKB5000_All_V3.211.10SA000.1.R.181204.BIN
	ConfigTool	General_ConfigTool_ChnEng_V4.011.0000000.0.R.20180906.zip
	PlaySDK	General_PlaySDK_Chn_Windows32_IS_V3.39.1.R.171130.zip
DSS	DSS7016	General_DSS70XXS2_Chn_Basic_Mysql_V1.000.0000002.0.R.20181102.tar.gz
	DSSPro	General_DSS-PRO_Win64_IS_V7.002.0000001.0.R.20181221.exe

## 1.6 Pending Issues

No.	Issue description	Possible result	How to fix
1	When panorama PTZ is enabled, after you log out, and then log in again, panoramic image can not be displayed.	Panoramic PTZ function can recover occassionally.	When producing panoramic images, do not log out the web; if you have logged out, download the plug-in again.
2	During pattern, zoom speed is changed, pattern again, the pattern function can not work normally.	—	Do not change zoom speed during pattern.

## 1.7 Update Guide

Do not disconnect your devices from the power source. If you have updated the program to this version, later versions cannot return to versions earlier than 2.800.

**ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.**

Address: No.1199, Bin'an Road, Binjiang District, Hangzhou, P.R. China

Postcode: 310053

Tel: +86-571-87688883

Fax: +86-571-87688815

Email: [overseas@dahuatech.com](mailto:overseas@dahuatech.com)

Website: [www.dahuasecurity.com](http://www.dahuasecurity.com)